

Distributor Notification

Important product safety and voluntary recall notice

Product: TM-10 (SKM-108500) & TMS-10 (SKM-108510)

Please read carefully and act upon the following recommendations

Dear Distributor,

11/01/2024

Skookum has recently determined that a small number of TM-10 Blocksides Heat Code 04-23 are out of our specifications. Out of an abundance of caution, we are issuing this voluntary recall notification for all TM-10 Blocks with Heat Code 04-23.

Please inspect your inventory for any Skookum TM-10 Block (SKM-108500) and TMS-10 Blocks (SKM-108510) with heat code 04-23. You will find the heat code at the top of the Blockside as indicated in the yellow box in the photo below.



If you have any of these TM-10 or TMS-10 blocks in your possession or in the field that can be called back, please isolate them and contact Skookum for a Return Material Authorization and return shipping instructions.

Sales@skookumtough.com 503-651-3175